• CHU/QBE refusing valid insurance claim on false stateent that the damage to two phases of power supply to lift in Block A was caused by "building movement"!? In fact, it was caused by unprofessional work by electricians who were secretly involved in unapproved work to provide additional power to the complex to accommodate needs of Optus for unapproved instalation of mobile tower on top of Block C. The alleged two-phase loss in Block A occurred in broad daylight whilst electricians were on site. No earthquake or billding movements were recorded on that day.

From:	Josephine_Chan
Sent:	Friday, 10 December 2010 3:28 PM
To:	Ron Sinclair
Subject:	Re: Re: SP52948 - Claim: Power Cable Failure
Attachme	nts: 1537_001.pdf
Hi Ron,	
the new rep	above matter and our subsequent discussions with CHU to re-consider the claim based on ort from the Electrical Solutions. -looked at the matter, and unfortunately, has denied the claim under Policy 1 Exclusion as pe
[QUOTE]	
Hi Josephine,	
reviewi	ng the report it appears the failure occurred due to movement within the slab.
We draw you	r attention to exclusions under Policy 1 Exclusion which states;
We will not p	ay for:
m) Norm walls, bridges	al settling, creeping, heaving, seepage, shrinkage, or expansion in buildings, foundations/footpaths, , roadways, kerbing, driveways, paths, garden borders and other structural improvements.
regard to you	thing we can to provide quality service. If you have a query about the decision we have made in r policy or claim or you would like to know more about the services available, including our dispute vice, please refer to your policy booklet.
Regards,	
John Gorman	Claims Consultant

CHU Underwriting Agencies Pty Ltd

• Electrical Solutions "explanation" of the power failure problem, carefully protecting themselves from insurance risks:

	ectrical Solutions Pty. Ltd. oject Engineering Consultants	4/127 Million Veda BM (k June HEDW 2075) P/J Mina HET Klastfand HOAW 2070 Phone Polls 211 U(2) Phone 1.22 (10082)HET	
	Incorporated in NSW A.B.N 67 040 594 894		
	e-1	nait electricalsolution/abigpond.com	
Wednesday,	22 September 2010		
RAINE & F 54 BEECRO EPPING NS	HORNE STRATA - SYDNEY OFT ROAD <u>SW 2121</u>		
Attention	Mr. John Fry		
Re:	Fontenoy Road Macquaric Park		
Dear John	1	loss to the lift in tower block A.	
1 attended s	Further to our brief conversation regarding the power loss to the lift in tower block A, I attended site with Peter Janzen to review the problem and do some further electrical		
room for A	g confirmed that the cable between the ma block lift, had shorted to earth on two phing nly able to carry out a limited inspection of ear that the full length of cable run is in co	of the cable route because it	
slab. The cable i	route length is approximately 150 metres (and the cable will have to be	
the new ca	s not appear to be any way to pull the exist able will have to be installed on cable tray, ge roof slab.	Comp and	
	e roof slab. tely this is a difficult task because of the b the existing fire services and piping (such	eam structure of the garage root as Gas and storm water/sewage	
lines) The cable	s have to be fire rated because it will be su	applying a lift, which is classified	
I would e	stimate that the cost of this installation will	he common services distribution	
board but loading p	made a preliminary power connection to t t this is only temporary and will have to be roblems until the permanent connection is ake of expediency. I have asked Terry Jam	made. sen and one other Contractor for a	
price, as quotation	the major players would have a lew weeks	, icali inice to even property	
	Ради 1		

4/187 Mona Vale Rd St. Ives. MSW 3073 Electrical Solutions Pty. Ltd. ES **Project Engineering Consultants** Incompreted in NSW A.B.N 67 003 594 894 e-mail electricalsolution@higpond.com 21 November 2010 RAINE & HORNE STRATA - SYDNEY 54 BEECROFT ROAD EPPING NSW 2121 Attention Mr. John Fry Fontenoy Road - Macquarie Park Re: Lift Cable Failure Dear John I have reviewed the comments contained in the CHU letter of claim rejection, dated 12th October 2010, as requested. The failure of the cable supplying power to the lift motor room in residential block A was not a result of the reason as set down in CHU Policy Exclusion 1 (e) which primarily applies to the cables within the lift shafts and lift cars rather than the actual supply to the lift motor room control panel. The cable failed is due to a short circuit between two phases of the three phase supply cables between the main switchboard and the lift motor room distribution board. This power supply was originally installed in electrical protective conduits set into the concrete construction slab. There are two separate conduits in the lift cable run. The two phase cables that have a short circuit between them are in the same conduit. The overall conduit lengths are approximately 150 metres and do not appear to leave the concrete slab at any other location other than the start and finish of the run. The cable size selection appears to be within the cable ratings as set down in AS3000 (as applicable at the time of installation). There are no indicative signs of excessive power or current surges in any part of the lift installation that would lead to a conclusion of; Caused by overwinding, mechanical breakdown or derangement, electrical breakdown or derangement or failure caused by electric current. Page 1

(RS)

Electrical Solutions Pty, Ltd. Engineering Consultants 314 Pacific Highway Lisadioli NSW 2070 P.O. Bas 407 Lisadioli NSW 2070 Phone (02) 94164824 Fex (03) 94359258

Tests indicate that the failure has occurred within the concrete slab and would appear to have been cause by movement within the concrete slab itself, probable at an expansion joint, which could have crushed the conduit, causing the short between cables. The exact location could not be determined in our preliminary investigations.

It is usual to find some other signs of overload or excessive overheating that would cause cable damage, but none is evident either in the supply switchboard or the lift distribution switchboard. There is no evidence of damage to any other part of the installation.

Yours faithfully,

R. H. Taylor

Page 7.

(mig

• Electrical Solutions secretly charging for change in design after proposal for Optus mobile tower installation was rejected by owners corporation:

ES Electrica	I Solutions Pty. Ltd.	4/187 Meen Vole Bill St. Den, NSW 2075	
	gineering Consultants	P.D. Buss 407 Conditiond NDW 2079 Phone 0438-251-652	
	Incorporated in NSW	Pase (0.2) WHERE AND	
12.3	A.B.N 67 003 594 894	icalsolution@bigpond.com	
	C man cicca	แหละรางแหงสุรัตรัฐสุรสารสารท	
	TAX INVOICE	s.p. 52948	
	INVOICE No. 2011/01/12	Authorizasi 2211	
Friday, 7 January 20	011	Cast 100273	
RAINE & HORNI P. O. BOX 881	E STRATA - SYDNEY	Ammon H290.	
EPPING NSW 17	710	Consultant	
ATTENTION:	Accounts Payable	Ace Code 119	
Project:	1-15 Fontenoy Road, Macquarie Park	Ref: Mr. John Fry	
amps, an - Location undergro	e additional restrictions and costs associated with d resubmission of documentation for switchboard of existing consumers mains into the complex ar- und cable route to minimise the constructional in	d design, id replanning the new	
 Negotial clearanc Supervis construct Supervis Energy Final in: Fee for Serve 	tions with Energy Australia for power outage e documentation, sion of cable installation works and inspectio tion, ision of switchboard installation and connecti Australia power shutdown, spections in conjunction with and acceptance ices I hours to end December 2010 (project completio 39 hours GST Total Amount Payable	s (three in all) and all safety ns of new switchboard ons in conjunction with the by Energy Australia. n) \$ 3900 - 00 \$ 390 - 00 \$ 4290 - 00	
 Negotial clearanc Supervision construct Supervision Supervision Final interpretation Fee for Service Tota 	tions with Energy Australia for power outage e documentation, sion of cable installation works and inspectio tion, ision of switchboard installation and connecti Australia power shutdown, spections in conjunction with and acceptance ices I hours to end December 2010 (project completio 39 hours GST	s (three in all) and all safety ns of new switchboard ons in conjunction with the by Energy Australia. n) \$ 3900 - 00 \$ 390 - 00 \$ 4290 - 00	
Negotial clearanc Supervis construc Supervis Energy Final in: Fee for Serv Tota With Compliments,	tions with Energy Australia for power outage e documentation, sion of cable installation works and inspectio tion, ision of switchboard installation and connecti Australia power shutdown, spections in conjunction with and acceptance ices I hours to end December 2010 (project completio 39 hours GST Total Amount Payable	s (three in all) and all safety ns of new switchboard ons in conjunction with the by Energy Australia. n) \$ 3900 - 00 \$ 390 - 00 \$ 4290 - 00	
Negotial clearanc Supervis construc Supervis Energy Final in: Fee for Serv Tota With Compliments,	tions with Energy Australia for power outage e documentation, sion of cable installation works and inspectio tion, ision of switchboard installation and connect Australia power shutdown, spections in conjunction with and acceptance ices i hours to end December 2010 (project completio 39 hours GST Total Amount Payable Page 1 of 1mv 110112 Baine & 1	s (three in all) and all safety ns of new switchboard ons in conjunction with the by Energy Australia. n) \$ 3900 - 00 \$ 390 - 00 \$ 4290 - 00	
Negotial clearanc Supervis construct Supervis Energy Final in: Fee for Serv Tota With Compliments, K.H. TAYLOR	tions with Energy Australia for power outage e documentation, sion of cable installation works and inspectio tion, ision of switchboard installation and connect Australia power shutdown, spections in conjunction with and acceptance ices i hours to end December 2010 (project completio 39 hours GST Total Amount Payable Page 1 of 1mv 110112 Baine & 1	s (three in all) and all safety ns of new switchboard ons in conjunction with the by Energy Australia. n) \$ 3900 - 00 \$ 390 - 00 \$ 4290 - 00	