Contents – SP52948 examples of replacements of smoke detectors from common funds

Essential Services Management – charged common funds for visit to Unit 110 to replace smoke detector whe	n
owner did not provide access – 10 October 2013	2
Essential Services Management – replaced smoke detector Unit 162 – 6 December 2010	3
Essential Services Management – replaced smoke detector Unit 117 – 15 November 2013	4
Essential Services Management – replaced smoke detector Unit 146 – 9 December 2013	5
Essential Services Management – replaced faulty smoke detector Unit 79 – 31 October 2014	6
Essential Services Management – replaced smoke detector Unit 79 – 20 November 2014	7
Essential Services Management – replaced faulty smoke detector Unit 145 – 6 May 2015	8
Essential Services Management – replaced faulty smoke detector Unit 106 – 4 August 2015	9
Essential Services Management – replaced faulty smoke detector Units 108 and 159 – 12 May 2015	. 10
Essential Services Management – replaced smoke detector Townhouse 200 – 31 August 2015	. 11
Essential Services Management – replaced faulty smoke detector Townhouse 198 – January 2016	. 12
Essential Services Management – replaced second faulty smoke detector Unit 183 – February 2016	. 13
Essential Services Management – replaced faulty smoke detector Unit 182 – 12 February 2016	. 14
Essential Services Management – replaced second faulty smoke detector Townhouse 198 – April 2016	. 15
Essential Services Management – replaced faulty smoke detector Unit 68 – 19 May 2016	. 16
Essential Services Management – replaced faulty smoke detector Unit 180 – 9 August 2016	. 17
Essential Services Management – replaced second smoke detector Townhouse 200 – 24 August 2016	. 18

Essential Services Management – charged common funds for visit to Unit 110 to replace smoke detector when owner did not provide access – 10 October 2013



PLEASE PAY BY 24 Oct 2013 10 Oct 2013

TAX INVOICE NO. 3361

BCMS, Raine & Horne - Sydney Locked Bag 22. Haymarket. NSW 1238 Job No: 2030 Site: Strata Plan 52948 Site Address: 1-15 Fontancy Rd

Macquaria Park NSW 2113
Order No.: Verbai - Steven 2/9/2013

Request No.:

Description

Work Requested: Please attend site and make repairs as necessary

Reported faulty smoke alarm Unit 110

Work Performed:

Attended site 02/09/2013 Investigate operation operation of faulty smoke alarm as advised by Steve. No Access available

Electrical Service

Electron Management thanks you for selecting us as one of your preferred Electrical contractors

Quantity	Bigging Control of the Control of th
1.00	Call Out Amanda
\$80.00	Sub-Total ex GST
\$8.00	CONTROL CONTRO
\$88.00	Total
_	Total

Essential Services Management – replaced smoke detector Unit 162 – 6 December 2010

Extract from SP52948 Cash Management for the financial 01/09/2010 to 30/06/2011:

6/12/2010	EFT: 000266	Electron Management Pty Ltd: U162 - Replace smoke	165.00
		detector	

Essential Services Management – replaced smoke detector Unit 117-15 November 2013

Extract from SP52948 Cash Book Payments by account code 2013/2014:

				•••••
Fire Services	15/11/2013 00990826	UNIVERSAL PROPERTY SERVICES	58.00	U117-SMOKE DETECTOR

Essential Services Management – replaced smoke detector Unit 146 – 9 December 2013

Extract from SP52948 Cash Book Payments by account code 2013/2014:

Fire Services	9/12/2013 00990856	UNIVERSAL PROPERTY SERVICES	116.00	U146-SMOKE DETECTORS

Essential Services Management – replaced faulty smoke detector Unit 79 – 31 October 2014



www.electronmanagement.com.au

PLEASE PAY BY 15/11/2014

\$182.59

INVOICE DATE 01/11/2014

TAX INVOICE NO. 4829

Body Corporate Services (BCS) Locked Bag 22. Haymarket, NSW 1238

Job No: 3816

Site: Strata Plan 52948 Site Address: 1-15 Fontenoy Rd Macquarie Park NSW 2113

462648 Order No.:

Request No.:

Description

Work Requested: Please attend site and make repairs as necessary

Please attend to the smoke alarm in unit 79, reported not to be functioning correctly.

Work Performed:

Attended site 31/10/2014 investigate operation of smoke alarm, identify faulty and install new 240v ionization smoke alarm as required

Electrical Service

Electron Management thanks you for selecting us as one of your preferred Electrical contractors

4 Hem		Quantity
Call Out		1.00
Brooks 240v 9v Battery - Ionization		1.00
Tradesmen		0.25 hrs
nwice-sneen	Sub-Total ex GST	\$165.99
	GST	\$16.60
	Total	\$182.59

Essential Services Management – replaced smoke detector Unit 79 – 20 November 2014

Extract from SP52948 Cash Book Payments by account code 2014/2015:

Fire Services 20/11/2014 00991210 ESSENTIAL SERVICES MANAGEMENT 165.99 INSTALL NEW SMOKE ALARM U79



www.electronmanagement.com.au

15/11/2014

AMOUNT INVOICE DATE \$182.59 01/11/2014

TAX INVOICE NO. 4829

Body Corporate Services (BCS) Locked Bag 22. Haymarket, NSW 1238 Job No: 3816

Site: Strata Plan 52948 Site Address: 1-15 Fontenoy Rd Macquarie Park NSW 2113

Order No.: 482648

Order No.: 4626 Request No.:

Description

Work Requested: Please attend site and make repairs as necessary

Please attend to the smoke alarm in unit 79, reported not to be functioning correctly.

Work Performed:

Attended site 31/10/2014 investigate operation of smoke alarm, identify faulty and install new 240v ionization smoke alarm as required

Electrical Service

Electron Management thanks you for selecting us as one of your preferred Electrical contractors

tem		Quantity
Call Out		1.00
Brooks 240v 9v Battery - Ionization		1.00
Tradesmen		0.25 hrs
no constant	Sub-Total ex GST	\$165.99
	GST	\$16.60
	Total	\$182.59

Essential Services Management – replaced faulty smoke detector Unit 145 – 6 May 2015



ABN 90430636934

www.electronmanagement.com.au

PLEASE PAY BY 20/05/2015

\$196.35

INVOICE DATE 06/05/2015

TAX INVOICE NO. 5463

Body Corporate Services (BCS) Locked Bag 22. Haymarket. NSW 1238

Job No: 4555

Site: Strata Plan 52948 Site Address: 1-15 Fontenoy Rd Macquarie Park NSW 2113

Order No.:

Request No.: Verbal - Steve 4/5/15

Description

Work Requested: Please attend site and make repairs as necessary

Replace faulty smoke alarm Unit 145

Work Performed:

Attended site 5/5/15, Investigate operation of smoke detector

Replace faulty smoke detector in hallway with new Brooks 240v Ionisation smoke detector.

Electrical Service

Electron Management thanks you for selecting us as one of your preferred Electrical contractors

ltem .		Quantity
Call Out		1.00
Brooks 240v 9v Battery - Ionization		1.00
Tradesmen		0.50 hrs
	Sub-Total ex GST	\$178.50
	GST	\$17.85
	Total	\$196.35

Essential Services Management – replaced faulty smoke detector Unit 106 – 4 August 2015



Body Corporate Services (BCS) Locked Bag 22. Haymarket. NSW 1238

PLEASE PAY BY 18/08/2015

INVOICE DATE 04/08/2015

TAX INVOICE NO. 5903

Job No:

Site: Strata Plan 52948 Site Address: 1-15 Fontenoy Rd Macquarie Park NSW 2113

Order No.:

Request No.: Verbal - Steve 4/8/2015

Description

Work Requested: Please attend site and make repairs as necessary

Complete repairs as requested

Work Performed:

Attended site 04/08/2015 T

identify and replace faulty LED light fitting outside unit 68 as requested Replace faulty 240v smoke alarm in hallway of Unit 106

Electron Management

Electron Management thanks you for selecting us as one of your preferred Electrical contractors

ltem:		Quantity
Call Out		1.00
Brooks 240v 9v Battery - Ionization		1.00
Clevertronics 17.5w non emg non sensor		1.00
Tradesmen		1.00 hrs
	Sub-Total ex GST	\$363.71
	GST	\$36.37
	Total	\$400.08

Essential Services Management – replaced faulty smoke detector Units 108 and 159 – 12 May 2015



Licence # 240567C ABN 90430636934

www.electronmanagement.com.au

PLEASE PAY BY 27/05/2015

\$316.25

13/05/2015

TAX INVOICE NO. 5512

Body Corporate Services (BCS) Locked Bag 22. Haymarket. NSW 1238 Job No: 4600

Site: Strata Plan 52948 Site Address: 1-15 Fontenoy Rd

Macquarie Park NSW 2113

Order No.:

Request No.: Verbal - Steven 11/52015

Description

Work Requested: Please attend site and make repairs as necessary

Replace faulty smoke alarms Unit 159 & 108

Replace faulty weatherproof fluro fitting adj tennis court steps

Work Performed:

Attended site 12/05/2015 replace faulty smoke detectors Units 159 & 108 as instructed

Investigate operation of reported light. Identify and replace burnt starter

Electrical Service


Electron Management thanks you for selecting us as one of your preferred Electrical contractors

Item		Quantity
Call Out		1.00
Brooks 240v 9v Battery - Ionization		2.00
Starter - S2, S10		1.00
Fluorescent Tube - 36w		1.00
Tradesmen		1.00 hrs
	Sub-Total ex GST	\$287.50
	GST	\$28.75
	Total	\$316.25

Essential Services Management – replaced smoke detector Townhouse 200 – 31 August 2015

Extract from SP52948 Cash Book Payments by account code 2014/2015:

Fire Services 31/08/2015 00991528 ESSENTIAL SERVICES MANAGEMENT 141.00 REPLACE SMOKE ALARM 10/8 U200



Essential Services Management – replaced faulty smoke detector Townhouse 198 – January 2016

Extract from Uniqueco Property Services monthly report:

- 3. Electron Management:
 - D Block, Level 3 and Level 1 faulty light fitting was replaced.
 - b. C Block, Level 6 faulty light fitting was replaced.
 - c. Townhouse 198 replaced faulty smoke alarm.



Body Corporate Services (BCS) PO Box 610 Artarmon NSW 1570 PLEASE PAY BY AMOUNT INVOICE DATE 15/02/2016 \$280.50 01/02/2016

TAX INVOICE NO. 6653

Job No: 570 Site: Stra

Site: Strata Plan 52948 Site Address: 1-15 Fontenoy Rd Macquarie Park NSW 2113

Order No.: Request No.: Verbal steve 11/1/16

Description

Work Requested: Please attend site and make repairs as necessary

Reported faulty smoke alarm TH #198

Reported D block level 3 faulty light

Work Performed:

Attended site 14/1/16, Work as requested

Identify and replace faulty light in "D" Block Level 3 with new 32w circular oyster light fitting.

Identify and replace faulty smoke detector in unit #198 with new Brooks 240v, 9v Battery backup smoke detector

Electron Management

Electron Management thanks you for selecting us as one of your preferred Electrical contractors

Item	Quantity
Call Out	1.00
Fluorescent Fitting - 32w Circular, Clipsal Slimline	1.00
Brooks 240v 9v Battery - Ionization	1.00
Tradesmen	0.75 hrs
Sub-Total ex GST	\$255.00
GST	\$25.50
Total	\$280.50

Essential Services Management – replaced second faulty smoke detector Unit 183 – February 2016 Extract from Uniqueco Property Services monthly report:

3. Electron Management:

- a. 2nd February A Block, Level 2 and Level 6 faulty light fitting was replaced.
- b. 12th February Unit 183 replaced faulty smoke detector.
- c. 12th February C Block, Level 5 replaced faulty light fitting.
- d. 17th February B Block, Level 5 replaced faulty light fitting.
- e. 24th February carried out the annual Eagle Fire replacement of Smoke Alarms, Emergency and Exit lights.
- f. 24th February Unit 181 replaced faulty porch light fitting.

Essential Services Management – replaced faulty smoke detector Unit 182 – 12 February 2016



Body Corporate Services (BCS) PO Box 610 Artarmon NSW 1570

PLEASE PAY BY 26/02/2016

\$214.84

INVOICE DATE 12/02/2016

TAX INVOICE NO. 6774

Job No: 5898

Strata Plan 52948 Site: Site Address: 1-15 Fontenoy Rd
Macquarie Park NSW 2113

Order No.: 1-15 Fontenoy Rd
Request No.: Steve - Verbal 10/2/16

Description

Work Requested: Please attend site and make repairs as necessary

Unit #182 Reported faulty/broken smoke detector

Please inspect and replace if faulty

Work Performed:

Attended site (12/02/2016) investigate operation of smoke alarm Unit 182

Identify smoke alarm faulty, supply and install new smoke alarm outside main bathroom as required

Electron Management

Electron Management thanks you for selecting us as one of your preferred Electrical contractors

Rem	Quantity
Call Out	1.00
Brooks 240v Lithium Battery - Ionization	1.00
Tradesmen	0.25 hrs
Sub-Total ex GST	\$195.31
GST	\$19.53
Total	\$214.84

Essential Services Management – replaced second faulty smoke detector Townhouse 198 – April 2016

Extract from Uniqueco Property Services monthly report:

- Electron Management:
 - a. C Block Ground Floor and Level 6 replaced faulty light fittings.
 - Fitting missing Fire Door Compliance Tags to units in accordance with Eagle Fire's Annual Inspection report.
 - c. Townhouse 198 replaced faulty smoke detector.
 - d. A Block Level 3 replaced faulty light fitting.



fem .	Quantity
Call Out	1.00
Brooks 240v 9v Battery - Iontzation	1.00
Tradesmen	0.25 hrs
Sub-Total ex GST	\$161.00
GST	\$16.10
Total	\$177.10

Sub-Total ex GST	\$161.00
GST	\$16.10
Total Inc GST	\$177.10
Amount Applied	\$0.00
Balance Due	\$177.10

Essential Services Management – replaced faulty smoke detector Unit 68 – 19 May 2016



Body Corporate Services (BCS) PO Box 610 Artarmon NSW 1570

PLEASE PAY BY INVOICE DATE 07/06/2016 \$199.10 24/05/2016

TAX INVOICE NO. 7301

Job No:

Strata Plan 52948 Site:

Site Address: 1-15 Fontenoy Rd Macquarie Park NSW 2113

Order No.: Verbal - Steve Request No.: 1-15 Fontency

Description

Work Requested: Please attend site and make repairs as necessary

Replace faulty smoke alarm as required

Work Performed:

Attended site 19/5/16, Investigate operation of smoke detector

Identify and replace faulty smoke detector inside Unit #68 with new 240v 9v battery backup Ionisation smoke detector.

Electron Management

Electron Management thanks you for selecting us as one of your preferred Electrical contractors

llem	Quantity
Call Out	1.00
Brooks 240v 9v Battery - Ionization	1.00
Tradesmen	0.50 hrs
Sub-Total ex GST	\$181.00
GST	\$18.10
Total	\$199.10

Essential Services Management – replaced faulty smoke detector Unit 180 – 9 August 2016



Body Corporate Services (BCS) PO Box 610 Artarmon NSW 1570

PLEASE PAY BY INVOICE DATE 23/08/2016 09/08/2016

TAX INVOICE NO. 7698

6942

Job No: Site: Strata Plan 52948 Site Address: 1-15 Fontency Rd Macquarle Park NSW 2113

Order No.: 180/1-15 Fontency

Description

Work Requested: Please attend site and make repairs as necessary.

Replace faulty smoke detector unit 180

Work Performed:

Attended site (03/08/2015)

Replaced faulty smoke detector in unit with new 240v photoelectric smoke detector

(Existing location directly next to kitchen and shower, tenant reported detector in alarm state during shower and cooking

Electron Management
Electron Management thanks you for selecting us as one of your preferred Electrical contractors

flam	Quantity
Call Out	1.00
Smoke Alarm Photoelectric 240v - PSA	1.00
Tradesmen	0.25 hrs
Sub-Total ax GST	\$193.25
GST	\$19.33
Total	\$212.58

Sub-Total ex GST	\$193.25
GST	\$19.33
Total Inc GST	\$212.58
Amount Applied	\$0.00
Balance Due	\$212.58

Essential Services Management – replaced second smoke detector Townhouse 200 – 24 August 2016



Body Corporate Services (BCS) Locked Bag 22. Haymarket. NSW 1238 PLEASE PAY BY AMOUNT INVOICE DATE 07/09/2015 \$155.10 24/08/2015

TAX INVOICE NO. 5974

Job No: 5037

Site: Strata Plan 52948 Site Address: 1-15 Fontenoy Rd Macquarie Park NSW 2113

Order No.: Verbal peter

Request No.:

Description

Work Requested: Please attend site and make repairs as necessary

Reported faulty smoke alarm Unit 200

Work Performed:

Attended site 10/08/2015 investigate and replace faulty smoke alarm outside bedroom on the top floor

Electron Management

Electron Management thanks you for selecting us as one of your preferred Electrical contractors

llem .	Quantity
Call Out	1.00
Brooks 240v 9v Battery - Ionization	1.00
Sub-Total ex GST	\$141.00
GST	\$14.10
Total	\$155.10