

Sheet1

| SP52948 Eagle Fire Protection Inspections and Quotes to rectify deficiencies 2013 | January 2013 | July 2013 |
|---|---------------------|---------------------|
| Emergency and Exit Lights | \$17,955.00 | \$22,145.00 |
| Hose Reels | \$525.00 | \$805.00 |
| Fire Hydrants | \$270.00 | \$1,350.00 |
| Common Area Fire Doors | \$0.00 | Not Reported |
| Unit Entry Doors, Unit Smoke Alarms and Equipment | \$0.00 | Not Reported |
| Fire Extinguishers | Not Reported | \$135.00 |
| Subtotal | \$18,750.00 | \$24,435.00 |
| Total (with GST) | \$20,625.00 | \$26,878.50 |
| The increase in cost to rectify deficiencies for fire protection in period January to July 2013 amounts to | 30.32% | |