


ThyssenKrupp Elevator SERVICE REPORT



Building: Macquarie garden Job No: 2031857 Date: 15/12/14

Mechanics: 1: mai.w 2: _____ Lift ☒ Esc/MW ☐ Other _____

Mandatory Risk Assessment

Hazard	RR	Controls	Tick	NR
Working at Height	<u>2</u>	RCD		
Electrocution	<u>2</u>	Fire Extinguisher / Fire Blanket		
Energised Equipment, Plant, Services	<u>2</u>	Lock Out Tagout		
Manual Handling		EWP / Scaffold	☒	☒
Entanglement		Fall Arrest/PPE		
Slip / Trip / Fall		Mechanical Lifting / 2 Man Lift / Breakdown Load		
Hazardous Substances		MSDS / Spill Kits	☒	
Poor Housekeeping		Isolation, Barricades, Signage		
Crushing		Remove all Waste, and Trip Hazards		
Pinch Points		Insulation of Tools & Equipment		
		Lead Hooks, Lead Stands		

Maintenance Record

Every Visit:

1. Contact Customer ☐ 2. Ride Quality ☐ 3. Regular Checks ☐ 4. Emergency Telephone ☐

Maintenance Entered (Office):

Maintenance Program Tasks: Travel Time: _____ AM PM Time In: _____ AM PM Time Out: _____ AM PM

Description	Task Group =	Unit Number							

Call Out Report

Fault Reported: SWP on basement Unit No: 3

Repair: ☐ On Site Call: ☐ A/Hour Call: ☒ Charge: ☐ Group Fault: ☐ Follow Up: ☐

SWP: ☐ SWP on arrival: ☐ R.O.A.: ☐ Interference: ☐ Shut Down: ☐ Travel Time: _____ AM PM

Time In: _____ AM PM SWP Released: _____ AM PM Time In Service: _____ AM PM Time Out: 16:45 AM PM

Action Report:

passenger out on arrival, found processor lock-up, Reset same, also checked & cleaned-up lock on B Level, tested operation, could not fault, return to service

Material Used:

Call Out Entered (Office):

Call Log Number: 506426 Fault Code: Cx KVA

Service Order Charge Details

Charge Client: ☐ Charge Other: ☐ Cash Charge: ☐ Customer Order Number: _____

Client Name: _____ Client Phone Number: _____

Client Address: _____

Client Signature: _____ Mechanic's Signature: _____

NSW 1300 799 599 VIC 1300 799 599 ACT 1300 799 599 SA 1300 799 599 WA 1300 799 599 TAS 1300 799 599 NT 1300 799 599 QLD 1300 652 899 NZ 9379 7798

White-Customer... Pink-Office... Green-Motor Room

1104804 V12

ROPEK PTY LTD

ABN 14 002 077 456 | SECURITY LICENCE 405359556

Unit 3, 183 - 185 McCredie Road Guildford NSW 2161

P 02 9681 1000 | F 02 9681 1946

service@ropek.com.au | www.ropek.com.au



SERVICE DOCKET No. 14073

CUSTOMER		CALL No.	22547
		DATE	
LOCATION	1-15 Fontenoy rd		Macquarie park NSW
2113		CONTACT	

CALL DETAILS	
password change	

DESCRIPTION	PARTS USED	PART NUMBER	QUANTITY

WORK PERFORMED	
* Defaulted system and programmed new user	
* Setup and checked ok ✓	

DATE	LOG IN	LOG OUT	LABOUR	STD. HOURS	O/T HOURS
			TRAVEL TIME		

TECHNICIAN Daniel

CLIENTS NAME Ruth Luka

SIGNATURE [Signature]

TICK BOX TO DESCRIBE WORK PERFORMANCE

COMPLETE ☐ INCOMPLETE ☐

WARRANTY ☐ AGREEMENT ☐ CHARGE ☐