

## Contents

SP52948- Rusted lock on tennis court unattended for three years - 23 <sup>rd</sup> of June 2019.....	2
SP52948- Rusted lock on tennis court - rushed but incomplete repair after owner's complaint - 13 <sup>th</sup> of July 2019	3
SP52948- Rusted lock on tennis court - paint after second owner's complaint about incomplete repair - 11 <sup>th</sup> of August 2019.....	4
SP52948- Rusted lock on tennis court - hiding incomplete rust-proof painting inside the lock - 15 <sup>th</sup> of August 2019.....	6
SP52948- Rusted tennis court 2 pole destroyed net - 10 <sup>th</sup> of August 2019.....	7
SP52948- Rusted tennis court 2 pole destroyed net - 11 <sup>th</sup> of August 2019.....	9
SP52948- Rusted tennis court 1 pole - 15 <sup>th</sup> of August 2019.....	11
SP52948- Examples of tennis court fence damages and sharp wires protruding that caused scratch injuries to female owner on 15 <sup>th</sup> of September 2019.....	12

SP52948- Rusted lock on tennis court unattended for three years - 23<sup>rd</sup> of June 2019



SP52948- Rusted lock on tennis court - rushed but incomplete repair after owner's complaint - 13<sup>th</sup> of July 2019



SP52948- Rusted lock on tennis court - paint after second owner's complaint about incomplete repair - 11<sup>th</sup> of August 2019






SP52948- Rusted lock on tennis court - hiding incomplete rust-proof painting inside the lock - 15<sup>th</sup> of August 2019



SP52948- Rusted tennis court 2 pole destroyed net - 10<sup>th</sup> of August 2019



2019-08-10 15:56:56



SP52948- Rusted tennis court 2 pole destroyed net - 11<sup>th</sup> of August 2019



2019-08-11 07:58:13




2019-08-11 07:58:41


SP52948- Rusted tennis court 1 pole - 15<sup>th</sup> of August 2019



SP52948- Examples of tennis court fence damages and sharp wires protruding that caused scratch injuries to female owner on 15<sup>th</sup> of September 2019







2019-09-15 08:53:43



2019-09-15 08:53:31